PW127M (BS 1237) ESN: AV0060 TM / EB0125 RGB

Engine details for reference: Preliminary data and subject to change.

TM		RGB	
TSN	34,881.21	TSN	27,210.21
CSN	42,037	CSN	30,068
TSO	0	TSO	0
CSO	0	CSO	0
TSHSI	0		0
TSR	0	TSR	0
CSR	0	CSR	0

Latest Maintenance Info		
Event	**Date**	**Provider**
OH	Projected April 1, 2027	StandardAero

Description	Part No.	CSN	Cycle Limit	TCR
LP Impeller	3073138-01	0	15,000	15,000
LP Turbine	3039412	0	15,000	15,000
HP Cover, Front	3039640	0	15,000	15,000
HP Cover, Rear	3039639	0	15,000	15,000
HP Impeller	3073133-01	0	15,000	15,000
HP Turbine	3041511	0	15,000	15,000
PT Stg. 1 Turbine	3038513	0	30,000	30,000
PT Stg. 2 Turbine	3033914	0	30,000	30,000
Inter Stg. Air Seal	3039172	0	15,000	15,000
HP Blades (38)	3115601-01	0	15,000	15,000
PT Blade, 1st Stg (18)	3078563-01	0 TSN	25,000 hr. Soft Time	
PT Blade, 1st Stg (48)	3078563-01	9,603.06 TSN		
PT Blade, 2nd Stg (71)	3135487	0 TSN		

Notes: For all PW127 series engines, HP Blades P/N: 3115601-01 have a 3,000 hour soft time limit per SIL PW100-183 & the applicable Maintenance Manual.

Contact:
Kevin Poulin - Director Engine Trading
Kevin.poulin@standardaero.com Phone: 616.499 1432

Contact:
Tommy McAdam – Portfolio Asset Manager
Tommy.mcadam@standardaero.com Phone: 902.315.4761


StandardAero