PW127M (BS 1237) ESN: ED0579 TM / RGB

Engine details for reference: Preliminary data and subject to change.

TM		RGB	
TSN	22,026.7	TSN	22,026.7
CSN	22,651	CSN	22,651
TSO	0	TSO	0
CSO	0	CSO	0
TSHSI	0		N/A
TSR	0	TSR	0
CSR	0	CSR	0

Latest Maintenance Info		
Event	**Date**	**Provider**
OH	Projected Dec. 31, 2026	StandardAero

Description	Part No.	CSN	Cycle Limit	TCR
LP Impeller	3073138-01	0	15,000	15,000
LP Turbine	3039412	0	15,000	15,000
HP Cover, Front	3039640	0	15,000	15,000
HP Cover, Rear	3039639	0	15,000	15,000
HP Impeller	3073133-01	0	15,000	15,000
HP Turbine	3041511	0	15,000	15,000
PT Stg. 1 Turbine	3038513	11,133	30,000	18,867
PT Stg. 2 Turbine	3033914	11,133	30,000	18,867
Inter Stg. Air Seal	3039172-02	0	15,000	15,000
HP Blades (38)	3115601-01	0	15,000	15,000
PT Blade, 1st Stg (66)	3123943-01	0	25,000 hr. Soft Time	

Notes: For all PW127 series engines, HP Blades P/N: 3115601-01 have a 3,000 hour soft time limit per SIL PW100-183 & the applicable Maintenance Manual.

Contact:
Kevin Poulin - Director Engine Trading
Kevin.poulin@standardaero.com Phone: 616.499 1432

Contact:
Tommy McAdam – Portfolio Asset Manager
Tommy.mcadam@standardaero.com Phone: 902.315.4761