

Brisbane Facility

An Industry-Leading MRO Facility

StandardAero's Brisbane, QLD, location is Australia's only Pratt & Whitney Canada PT6A Designated Overhaul Facility (DOF). Formally opened in 2013, the Brisbane facility offers OEM-authorized support for over 50 variants of the PT6A turboprop family, supported by an on-site test cell, in-house component repair capabilities, and extensive field service coverage.

Supporting the Asia-Pacific Region

As a P&WC authorized PT6A DOF, StandardAero's Brisbane location provides operators with the highest levels of support. Thanks to our extensive in-house component repair capabilities, we are also able to provide customers with a range of cost-effective MRO solutions, utilizing used serviceable materials and a 'repair rather than replace' philosophy. In addition, the Brisbane shop providers field service and engine repairs on the JT15D, PT6T, PW100 and PW300 engines, including on-site repairs at customer locations as well as responsive aircraft on ground (AOG) support.

StandardAero — The Right Choice

StandardAero's Brisbane facility holds a wide range of approvals, including CASA Part 145, EASA Part 145, FAA Part 145, ISO 9001:2008 and AS9110A. The facility also holds approvals from numerous local civil aviation authorities from across the Asia-Pacific region, including China, India, Indonesia and Thailand. No matter where you're located, we're the right choice to keep you flying!

To find out more about our capabilities or a site tour contact your area representative or visit http://www.standardaero.com

30 Industry Court Eagle Farm, Brisbane, QLD 4009, Australia Phone +61 (7) 3268.0000



www.standardaero.com

Facility Overview

- P&WC authorized Designated Overhaul Facility for PT6A, with Distribution rights
- Additional mobile repair technician (MRT) support for PT6T, PW100, PW300 & JT15D
- 22,000 ft² of shop space
- On-site test cell
- Component repair capabilities

Site Capabilities

Engine Maintenance, Repair & Overhaul

ΡΤ6Δ

-11, -11AG, -15AG, -20A, -21, -25, -25A, -25C, -27, -28, -34, -34AG, -34B, -35, -36, -38, -41, -42, -42A, -45A, -45B, -45R, -50, -52, -60A, -60AG, -61, -62, -64, -65AG, -65AR, -65B, -65R, -66A, -66B, -66D, -67, -67A, -67AF, -67AG, -67B, -67D, -67F, -67P, -67R, -67T, -110, -112, -114, -114A, -116, -121, -135, -135A

Field Service Support

PT6A

Services include HSI, AGB repairs, LCF change, and borescope inspection

- PW100

Services include HSI, LCF change, RGB removal/install and borescope inspection

■ JT15D

Including HSI, borescope inspection, fan blade replacement and FOD repair

■ PW300

Services include borescope inspection, fan blade replacement and AGB repairs

PT6T

Services include HSI, borescope inspection, AGB repairs and on-wing 2,500 hr inspection

