BIGGER. BETTER. BOLDER.



GE T700/CT7 Support Capabilities





As a worldwide leader in helicopter maintenance, repair, and overhaul, StandaerdAero is committed to providing the highest standards of quality, reliability, and customer service to more than 3,000 customers in over 85 nations.

StandardAero has an established reputation as a provider of T700/CT7 MRO services to military and civil operators worldwide. Our customers include:

- Royal Canadian Air Force
- Royal Netherlands Air Force
- Royal Thai Navy
- Royal Jordanian Air Force
- Egyptian Air Force
- UAE Joint Air Command
- Swedish Armed Forces
- Colombian Armed Forces
- Various U.S. civil and public use operators

We have a demonstrated commitment to delivered excellence, including TAT, pass-off performance and warranty support. As a GE-authorized T700/CT7 MRO provider, our services meet or exceed OEM standards.

Our Canadian-based T700/CT7 MRO facility is supported by a global network of 20 StandardAero facilities and a Mobile Repair Team (MRT) of 150 dedicated employees worldwide.

In addition to T700 MRO, StandardAero offers capabilities for cross-fleet support, including MRO on other turboshaft engine models, helicopter airframe and dynamic component MRO, engine accessory MRO, and aircraft management and design services.

StandardAero is the first independent MRO specialist to be appointed as a GE T700 Authorized Maintenance, Repair and Overhaul Provider (AMROP). This designation allows full access to OEM technical data and specifications, ensuring high-quality MRO services.

StandardAero is also one of only two independent MRO providers to be awarded U.S. DoD T700 source approval (Army & Navy).

T700/T6A1 (DND)**

T700-GE-401B*

Variants supported:



CT7-2A*



T700-GE-401*



T700-GE-700*



T700-GE-701A*



T700-GE-701C*



CT7-8A7 (DND)**



T700-GE-401C*



* Via AMROP T700-GE-701D* ** Via BLA



StandardAero offers a range of responsive, high-quality T700/CT7 services, including:

- Engine/module repair & overhaul
- In-house test cells
- Assembly, integration and test (AIT)
- Model conversions
- Failure analysis
- · Component repair

Our T700/CT7 component repair and overhaul (CRO) capabilities are as follows:


		use match s High spe	
	OEM	repairs In-ho	us High sh
Power turbine rotor components	٠		٠
Power turbine drive shaft components	٠	٠	
Power turbine stator components	٠	٠	
Exhaust frame components	٠		
Inlet section	٠		
Output shaft assembly	٠		
Compressor stator assembly	٠	٠	
Compressor rotor assembly	•	•	
Diffuser midframe assembly	•		
Fuel injector			
Combustion liner	•		
Gas generator rotor assembly		•	
Gas compressor stator assembly	٠	٠	







- Borescope inspection
- Foreign object damage (FOD) repair
- Parts support
- Service bulletin (SB) compliance
- · Engineering support
- Worldwide field service









Power Turbine Rotor & Drive Shaft Components

- OEM repairs (rotor & turbine)
- High speed match grinding (rotor)
- In-house ECI (rotor)
- In-house match grinding (turbine)
- EDM machining (turbine)




Exhaust Frame Components

OEM repairs




Output Shaft Assembly

- OEM repairs
- In-house flow capability




Power Turbine Stator Components

- OEM repairs
- In-house match grindingEDM machining




Inlet Section

OEM repairs




Compressor Stator Assembly

- OEM repairs
- In-house match grinding
- Re-coating




Compressor Rotor Assembly

- OEM repairs
- In-house match grinding
- In-house ECI
- Balancing




Diffuser Midframe Assembly


OEM repairs



Gas Generator Rotor Assembly


- In-house high speed match grinding
- In-house ECI
- In-house water flow
- Dynamic balancing






Fuel Injector

Pyrolizing cleaning & testing




Combustion Liner

OEM repairs



Gas Compressor Stator Assembly

- OEM repairs
- In-house match grinding



BIGGER. BETTER. BOLDER.

Richmond 20699 Westminster Highway Richmond, British Columbia, Canada V7C 4V4 Tel: +1 604.276.7600