

# Honeywell APUs

## Service Highlights:

- Honeywell APU Authorized Service Center & independent MRO provider
- Full MRO capabilities on GTCP36 and RE220 models
- Over 12,500 APUs processed
- Industry-leading turnaround times
- Rental / loaner APUs available
- Re-certification test cells
- In-house component repair, reducing the need for costly replacement parts
- Flexible program development to meet unique customer requirements
- Dedicated Field Service Teams and on-site engineering and technical support available 24/7
- Technical training
- Comprehensive warranty support and administration

## Facility Locations:

- **Augusta, GA**  
*Business aviation applications*
- **Maryville, TN**  
*Airlines/fleets & military applications*

## Contact Information

### Augusta, GA

Gregg Washburn (APU Crew Chief)  
+1 (706) 771-5631  
gregg.washburn@standardaero.com

### Maryville, TN

Randy Mengel (APU Program Director)  
+1 (865) 981-4697  
randy.mengel@standardaero.com



www.standardaero.com

© Copyright StandardAero 2018. All Rights Reserved.



## More Support. More Service. More Capability.

StandardAero is a Honeywell GTCP36 and RE220 APU Authorized Service Center, offering one-stop support and service. Our certified technicians give you the most comprehensive, experienced service in the industry from locations in Augusta, GA and Maryville, TN.

## Fast Turns To Get You Back In Service

Whether you operate a fleet of APUs or a single pack, we will support your needs with a combination of fast turn-times and world-class customer service. Our in-house processes restore your components to OEM specifications, protecting your bottom line, while our dedicated field service teams keep you flying, 24/7!

## Models Supported

| AUGUSTA, GA                  |                | MARYVILLE, TN       |                |
|------------------------------|----------------|---------------------|----------------|
| AIRCRAFT MAKE/MODEL          | APU MODEL      | AIRCRAFT MAKE/MODEL | APU MODEL      |
| BAe 125-700                  | GTCP36-100H    | A-10                | GTCP36-50      |
| Challenger 300/350           | GTCP36-150BD   | AH-64               | GTCP36-55C/H   |
| Challenger 600/601           | GTCP36-100E    | AH-64               | GTCP36-155H/LB |
| Challenger 604/605           | GTCP36-150CL   | BAe 146 / Avro RJ   | GTCP36-100M    |
| Citation III/VII             | GTCP36-150W    | BAe 146-300         | GTCP36-150M    |
| Citation X                   | GTCP36-150CX   | C-2A                | GTCP36-201C    |
| EMB-120                      | GTCP36-150A/AA | CRJ100/CRJ200       | GTCP36-150RJ   |
| Falcon 20-5                  | GTCP36-150W    | CRJ700/CRJ900       | RE220[RJ]      |
| Falcon 50                    | GTCP36-100A    | Dorner 328          | GTCP36-150DD   |
| Falcon 7X                    | GTCP36-150FN   | EMB-120             | GTCP36-150A/AA |
| Falcon 900/900EX             | GTCP36-150F    | F/A-18              | GTCP36-200     |
| Falcon 2000                  | GTCP36-150F2M  | Fokker 70/100       | GTCP36-150R/RR |
| Gulfstream G100              | GTCP36-150W    | SuperJet 100        | RE220[SJ/SSJ]  |
| Gulfstream G200/250 & Galaxy | GTCP36-150IAI  | UH-60/S-70          | GTCP36-150BH   |
| Gulfstream GIII/GIII/GIV     | GTCP36-100G    |                     |                |
| Gulfstream GIV/G300/G400     | GTCP36-150G    |                     |                |
| Hawker 800                   | GTCP36-150W    |                     |                |
| Hawker 4000                  | GTCP36-150HH   |                     |                |
| Legacy 450/500               | GTCP36-150EMB  |                     |                |

For AOG situations and emergency troubleshooting, please call us at: +1 (865) 380-2284  
For more information, visit <http://www.standardaero.com/engines/honeywell/APUs>