


# Component Services Capabilities

## LEAP-1B

Catalog



- Capabilities will be updated monthly and prices are subject to change at any time. Customers are encouraged to contact StandardAero for the newest list of pricing and repairs.
- StandardAero repairs and pricing provided are for typical part numbers and may not apply to all part numbers listed. Prices do not include SPAD material.
- Services provided by StandardAero shall be governed by the Component Services "Customer Terms & Conditions - Services", which are hereby incorporated in full by this reference, and are available at [www.standardaero.com/Portals/0/Documents/Legal/ComponentServicesCustomerTerms-Services.pdf](http://www.standardaero.com/Portals/0/Documents/Legal/ComponentServicesCustomerTerms-Services.pdf) or will be sent to Customer upon request. All Services provided to Customer are conditional upon acceptance of all of the terms and conditions on its face and incorporated herewith including the "Customer Terms & Conditions - Services." The terms may not be amended without StandardAero's written consent.

---

Date Printed: 27-Oct-2025 8:06 am



To inspire the best and constantly raise the Standard

**ATA Code : 72-21-01: FLOW PATH FAIRING****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-043-410-0 364-043-411-0 364-043-412-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-21-02: FLOW SPLITTER****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-504-001-0 364-909-000-0

C&amp;I Clean &amp; Inspect

R001 Blend Repair

R003 Shank Nut Replacement

R004 Two-Lug Nut Late and/or its Attachment Parts Replacement

**ATA Code : 72-21-03: FLOW PATH FAIRING HALF RING****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-091-510-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-21-20: FAN BLADES****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-040-902-0 364-040-904-0 364-040-907-0

C&amp;I Clean &amp; Inspect

R001 Blending (Metal Leading Edge)

R002 Leading and Trailing Edge and Platform Wear Strips Replacement

R004 Full Repair of Identification and Moments Weight Labels

R006 Coating Replacement (Local Repair of Platform Wear Strips with Polyurethane Paste)

R007 Coating Replacement

R009 Tip Repair

R011 Repair of Missing Polyurethane Film with PU Paste

**ATA Code : 72-21-21: LOW PRESSURE COMPRESSOR STAGE 1 VANE****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-509-601-0 364-901-000-0

C&amp;I Clean &amp; Inspect

R001 Blend Repair

**ATA Code : 72-21-22: LOW PRESSURE COMPRESSOR STAGE 2 VANE****Repair Location:** Cincinnati**Repair # Description**

**Part #:** 364-509-701-0 364-902-000-0

C&amp;I Clean &amp; Inspect

R001 Blend Repair

**ATA Code : 72-21-23: LOW PRESSURE COMPRESSOR STAGE 3 VANE****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-903-000-0

C&amp;I Clean &amp; Inspect

R001 Blend Repair

**ATA Code : 72-21-24: LOW PRESSURE COMPRESSOR STAGE 2 TO 4 BLADES****Repair Location:** Palm City**Repair # Description****Part #:** 364-906-090-0 364-906-190-0 364-906-290-0 364-906-390-0 364-907-090-0

364-907-190-0 364-907-290-0 364-907-390-0 364-908-090-0 364-908-190-0

364-908-290-0 364-908-390-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-21-25: LOW PRESSURE COMPRESSOR ROTATING SPACER****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-905-500-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-21-40: FRONT SPINNER****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-039-001-0

C&amp;I Clean &amp; Inspect

R001 Holes Blending

R002 Repair of the Anti-Erosion Paint, the White Spiral Mark and the Sulfuric Anodizing

**ATA Code : 72-21-42: FAN PLATFORM ASSEMBLY****Repair Location:** Cincinnati**Repair # Description****Part #:** 2620M62G01 2620M62G02 2620M62G03

C&amp;I Clean &amp; Inspect

R001 Wear Strip Replacement

R002 Part Marking Repair

R005 Seal Replacement

R006 Top Skin Local Repair

R008 Top Skin Local Repair (Area A3)

SB72-0068 Seal Replacement Per RD830-957

**ATA Code : 72-21-45: FAN DISK**

Repair Location: Cincinnati

Repair # Description

Part #: 364-040-010-0 364-040-011-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-21-49: LOW PRESSURE COMPRESSOR SPOOL**

Repair Location: Cincinnati

Repair # Description

Part #: 364-905-100-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-21-60: PLATFORM FRONT SHROUD**

Repair Location: Cincinnati

Repair # Description

Part #: 362-040-110-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-22-40: LOW PRESSURE COMPRESSOR SHAFT**

Repair Location: Cincinnati

Repair # Description

Part #: 364-045-010-0 364-045-020-0

C&amp;I Clean &amp; Inspect

R001 Coating Replacement

**ATA Code : 72-22-45: NO. 1 BEARING ROTATING SEAL**

Repair Location: Cincinnati

Repair # Description

Part #: 362-024-710-0 362-024-720-0

C&amp;I Clean &amp; Inspect

**ATA Code : 72-23-01: FAN CASE**

Repair Location: Cincinnati

Repair # Description

Part #: 364-050-013-0 364-050-014-0 364-050-016-0 364-050-099-0

C&amp;I Clean &amp; Inspect

R001 Repair of the Abradable Liner

R006 Fireproof Layer Local Repair

R007 Replace Acoustic Panel Brackets

**ATA Code : 72-23-02: ACOUSTIC SHROUD**

Repair Location: Cincinnati

Repair # Description

**Part #:** 364-062-101-0

C&amp;I Clean &amp; Inspect

R001 Impact Repair by Filling Up

**ATA Code : 72-23-03: ACOUSTIC PANELS****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-050-110-0

C&amp;I Clean &amp; Inspect

SPM Blend General Blend Repair per SPM

**ATA Code : 72-24-01: FAN FRAME SHROUD****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-049-151-0

C&amp;I Clean &amp; Inspect

R001 V-Groove Local Coating Repair

R004 Nut and/or Rivet Replacement

R005 Key-Locked Insert Replacement

**ATA Code : 72-24-04: FAN FRAME HUB****Repair Location:** Cincinnati**Repair # Description****Part #:** 362-029-135-0

C&amp;I Clean &amp; Inspect

R001 Insert Replacement

R002 Gang Channel Nuts, Two-Lug Nut Plates and Attaching Parts (Rivet)  
Replacement

SPM Blend General Blend Repair per SPM

**ATA Code : 72-24-06: OUTER OUTLET GUIDE VANE PLATFORMS****Repair Location:** Cincinnati**Repair # Description**

**Part #:** 364-053-631-0 364-053-731-0 364-053-831-0 364-053-931-0 364-054-031-0  
 364-054-131-0 364-054-231-0 364-054-331-0 364-054-431-0 364-054-531-0  
 364-054-631-0 364-054-731-0 364-054-831-0 364-057-331-0 364-057-431-0  
 364-057-531-0 364-057-631-0

C&amp;I Clean &amp; Inspect

R001 Damper Replacement

**ATA Code : 72-24-07: STRUT 1 FAIRING SUPPORT****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-039-110-0

C&amp;I Clean &amp; Inspect

R001 Nut Replacement

**ATA Code : 72-24-11: STRUT 5 OUTER FITTING****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-070-411-0

C&amp;I Clean &amp; Inspect

R002 Nut Replacement

**ATA Code : 72-24-20: OUTLET GUIDE VANES****Repair Location:** Kansas City**Repair # Description****Part #:** 364-052-011-0 364-052-211-0 364-052-411-0 364-052-611-0 364-052-711-0  
364-052-811-0 364-062-201-0 364-062-210-0 364-062-301-0 364-062-310-0  
364-068-111-0 364-068-211-0 364-068-311-0 364-068-511-0 364-068-611-0  
364-068-711-0 364-068-811-0 364-068-911-0

C&amp;I Clean &amp; Inspect

R002 Coating Replacement

R005 Blend of Leading and Trailing Edge

**ATA Code : 72-24-22: LOW PRESSURE COMPRESSOR STAGE 4 VANE****Repair Location:** Cincinnati**Repair # Description****Part #:** 364-510-503-0 364-904-000-0

C&amp;I Clean &amp; Inspect

R001 Blend Repair

**ATA Code : 72-24-36: NO. 3 BEARING STATIONARY OIL SEAL****Repair Location:** Kansas City**Repair # Description****Part #:** 2542M46P01

C&amp;I Clean &amp; Inspect

**ATA Code : 72-30-01: COMPRESSOR STATOR AFT EXTENSION CASE****Repair Location:** Cincinnati**Repair # Description****Part #:** 2552M42G05 2552M42G06 2552M42G07 2552M42G08

C&amp;I Clean &amp; Inspect

**ATA Code : 72-30-04: COMPRESSOR STATOR STAGE 6-7 AFT INNER CASE****Repair Location:** Cincinnati**Repair # Description****Part #:** 2551M97G02

R001 Should Pin Replacement

**ATA Code : 72-30-70: COMPRESSOR VANE ACTUATING BELLCRANK ASSEMBLY TURNB**

Repair Location: Cincinnati

Repair # Description

Part #: 2552M00G02 2552M00G03 2552M00G04

C&amp;I Clean &amp; Inspect

Assembly/Dis Assembly/Disassembly

**ATA Code : 72-31-20: COMPRESSOR ROTOR STAGE 6 BLADES**

Repair Location: Palm City

Repair # Description

Part #: P456P01 P456P02 P456P03 P456P04

C&amp;I Clean &amp; Inspect

R002 Airfoil Blend Repair

**ATA Code : 72-31-21: COMPRESSOR ROTOR STAGE 7 BLADES**

Repair Location: Palm City

Repair # Description

Part #: P317P01 P317P02 P317P03 P317P04

C&amp;I Clean &amp; Inspect

**ATA Code : 72-31-40: COMPRESSOR ROTOR STAGE 1 BLISK**

Repair Location: Cincinnati

Repair # Description

Part #: 2634M01G01 2634M01G02 2639M71G02

C&amp;I Clean &amp; Inspect

R001 Coating Repair of the Aft Arm Seal Teeth

R003 Castellation Slot Repair

**ATA Code : 72-31-41: COMPRESSOR ROTOR STAGE 2 BLISK**

Repair Location: Cincinnati

Repair # Description

Part #: 2552M02P02

C&amp;I Clean &amp; Inspect

R001 Blend Airfoils

R003 General Blend

**ATA Code : 72-31-42: COMPRESSOR ROTOR STAGE 3-4 BLISK**

Repair Location: Cincinnati

Repair # Description

Part #: 2552M03G02

C&amp;I Clean &amp; Inspect

**ATA Code : 72-31-43: COMPRESSOR ROTOR STAGE 5 BLISK**

**Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    2552M05P01 2552M05P02

C&amp;I            Clean &amp; Inspect

**ATA Code : 72-31-44: COMPRESSOR ROTOR STAGES 6-10 SPOOL****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    2552M06G01 2552M06G02 2552M06G03 2552M06G04

C&amp;I            Clean &amp; Inspect

**ATA Code : 72-31-45: IMPELLER TUBE SUPPORT****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    2552M07P01

C&amp;I            Clean &amp; Inspect

R001          Abradable Coating Repair

**ATA Code : 72-31-46: ROTATING SEAL****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    2552M09P01

C&amp;I            Clean &amp; Inspect

R001          Seal Teeth Coating Repair

R002          General Blend Repair

**ATA Code : 72-32-01: COMPRESSOR STATOR FORWARD CASE****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    2552M41G05 2552M41G06 2552M41G07

C&amp;I            Clean &amp; Inspect

R001          Bushings Replacement on the Variable Stator Vanes

**ATA Code : 72-32-20: COMPRESSOR STATOR STAGE 1 VANES****Repair Location:** Kansas City**Repair #**      **Description****Part #:**    P441G01 P451P02

C&amp;I            Clean &amp; Inspect

R001          Airfoil Blend Repair

**ATA Code : 72-32-21: COMPRESSOR STATOR STAGE 2 VANES****Repair Location:** Kansas City**Repair #**      **Description****Part #:**    P442G01 P452P02



C&I      Clean & Inspect  
 R001      Airfoil Blend

**ATA Code : 72-32-22: COMPRESSOR STATOR STAGE 3 VANES**

**Repair Location:**      Kansas City

**Repair #      Description**

**Part #:**      P443G01 P443G01

                 P453P02 P453P02

C&I      Clean & Inspect

R001      Airfoil Blend Repair

**ATA Code : 72-32-23: COMPRESSOR STATOR STAGE 4 VANES**

**Repair Location:**      Kansas City

**Repair #      Description**

**Part #:**      P444G01 P454P02 P464P02 P474G01

C&I      Clean & Inspect

R001      Airfoil Blend

**ATA Code : 72-41-01: COMBUSTION CASE ASSEMBLY**

**Repair Location:**      Cincinnati

**Repair #      Description**

**Part #:**      2548M30G01 2548M30G06 2548M30G07 2548M30G08

C&I      Clean & Inspect

C/I      Blend High Metal, Clean and Inspect - Combustion Case

SPM70-42-13 Replacement of Key-Locked Inserts

**ATA Code : 72-41-02: COMPRESSOR DISCHARGE PRESSURE STATOR SEAL**

**Repair Location:**      Cincinnati

**Repair #      Description**

**Part #:**      2548M41G01 2552M41G02 2552M41G05 2552M41G06 2552M41G07

C&I      Clean & Inspect

R001      Clinch Nut Repair

R002      Blend Honeycomb Repair

R003      Honeycomb Replacement

**ATA Code : 72-41-80: FUEL MANIFOLDS**

**Repair Location:**      Cincinnati

**Repair #      Description**

**Part #:**      2572M39G01 2572M40G01 2572M41G01 2585M70G01 2585M71G01

                 2585M72G01

C&I      Clean & Inspect

**ATA Code : 72-41-81: MODULATED TURBINE COOLING MANIFOLD ASSEMBLY**

**Repair Location:**      Cincinnati

**Repair #      Description**

**Part #:** 2548M46G02  
R002 Manifold upport Strap Replacement

**ATA Code : 72-42-01: DOMEPLATE ASSEMBLY**

**Repair Location:** Miami

**Repair # Description**

**Part #:** 2611M11G01 2611M11G02 2611M11G03

C&I Clean & Inspect

R002 Thermal Barrier Coating Removal

R003 Thermal Barrier Coating Replacement

SPM Blend Remove Raised Material per SPM

**ATA Code : 72-42-03: COMBUSTION CHAMBER OUTER LINER**

**Repair Location:** Miami

**Repair # Description**

**Part #:** 2559M23G03 2559M23G05

C&I Clean & Inspect

R001 Stg2-6 Borescope Ports Adapter

R002 Shank Nuts Replacement

**ATA Code : 72-42-05: COMBUSTION CHAMBER OUTER SUPPORT**

**Repair Location:** Miami

**Repair # Description**

**Part #:** 2611M12G01

C&I Clean & Inspect

R001 Self-Locking Nut Plates Replacement

R003 Re-size Repair

**ATA Code : 72-42-06: COMBUSTION CHAMBER INNER SUPPORT**

**Repair Location:** Cincinnati

**Repair # Description**

**Part #:** 1612M10G01

C&I Clean & Inspect

R001 Self-Locking Nut Plates Replacement

R004 Resize Repair

**ATA Code : 72-51-01: HIGH PRESSURE TURBINE FORWARD INNER NOZZLE SUPPORT**

**Repair Location:** Cincinnati

**Repair # Description**

**Part #:** 2548M11G07 2548M11G08 2548M11G09

C&I Clean & Inspect

R001 Honeycomb Seal Repair

R003 Shank Nut Replacement

R005 Repair of Wear on W-Seal Cavity

R006 Weld R&R of the Modulated Inducer Inlet

**ATA Code : 72-51-03: HIGH PRESSURE TURBINE OUTER STATIONARY SEAL**

Repair Location: Cincinnati

Repair # Description

Part #: 2548M16G01 2548M16G02

C&amp;I Clean &amp; Inspect

R001 Honeycomb Seal Replacement

**ATA Code : 72-52-20: HIGH PRESSURE TURBINE ROTOR STAGE 1 BLADES**

Repair Location: Cork

Repair # Description

Part #: 2010M42P01 2010M42P02 2010M42P03 2010M42P04 2010M42P05  
2010M42P06 2747M52P01 2747M52P02

C&amp;I Clean &amp; Inspect

**ATA Code : 72-52-40: HIGH PRESSURE TURBINE ROTOR STAGE 1 DISK**

Repair Location: Cincinnati

Repair # Description

Part #: 2600M21G02

C&amp;I Clean &amp; Inspect

**ATA Code : 72-52-41: HIGH PRESSURE TURBINE ROTOR STAGE 2 DISK**

Repair Location: Cincinnati

Repair # Description

Part #: 2547M01G01 2547M01G02 2547M01G03

C&amp;I Clean &amp; Inspect

R004 Clinch Nut Replacement

**ATA Code : 72-52-42: FORWARD OUTER SEAL**

Repair Location: Cincinnati

Repair # Description

Part #: 2596M44P02

C&amp;I Clean &amp; Inspect

R003 Coating Replacement

R004 Seal Teeth Coating Replacement

**ATA Code : 72-52-43: HIGH PRESSURE TURBINE ROTOR MID SEAL**

Repair Location: Cincinnati

Repair # Description

Part #: 2600M25P01 2600M25P02 2600M25P03

C&amp;I Clean &amp; Inspect

R005 T800 Coating Replacement

**ATA Code : 72-52-44: HIGH PRESSURE TURBINE AFT ROTATING SEAL****Repair Location:** Cincinnati**Repair # Description****Part #: 2547M40P02**

C&amp;I Clean &amp; Inspect

R002 Seal Teeth Coating Replacement

**ATA Code : 72-52-47: HIGH PRESSURE TURBINE ROTOR AIR DUCT****Repair Location:** Cincinnati**Repair # Description****Part #: 2547M08G01**

C&amp;I Clean &amp; Inspect

R001 Dry Film Lubricant Repair

R002 Repair of the Forward End (Diameter C)

**ATA Code : 72-52-60: HIGH PRESSURE TURBINE STAGE 1 BLADE RETAINER****Repair Location:** Cincinnati**Repair # Description****Part #: 2600M24P01**

C&amp;I Clean &amp; Inspect

**ATA Code : 72-52-90: HIGH PRESSURE TURBINE ROTOR COUPLING NUT****Repair Location:** Cincinnati**Repair # Description****Part #: 2547M12P01**

R001 Dry Film Replacement

**ATA Code : 72-53-01: HIGH PRESSURE TURBINE CASE****Repair Location:** Cincinnati**Repair # Description****Part #: 2541M81G01**

C&amp;I Clean &amp; Inspect

R003 Repair of the Aft Flange Rabbet

R005 Repair of the Forward Flange Rabbet

SPM Blend General Blend Repair per SPM

**ATA Code : 72-53-02: HIGH PRESSURE TURBINE STATOR STG 1 HANGER ASSY****Repair Location:** Cincinnati**Repair # Description****Part #: 2585M45G01 2585M45G02 2585M45G03**

C&amp;I Clean &amp; Inspect

SPM Blend General Blend Repair per SPM

**ATA Code : 72-53-05: HIGH PRESSURE TURBINE STATOR STAGE 2 HANGER****Repair Location:** Cincinnati**Repair # Description****Part #: 2551M41G01**

C&amp;I Clean &amp; Inspect

R001 Baffle Replacement

SPM Blend General Blend per SPM

**ATA Code : 72-53-80: HIGH PRESSURE TURBINE STG 2 NOZZLE IMPIGNEMENT RN****Repair Location:** Miami**Repair # Description****Part #: 2540M56G04 2540M56G05**

C&amp;I Clean and Inspect

R001 Weld Repair of Aft Flange

**ATA Code : 72-54-01: 4R BEARING HOUSING SUPPORT****Repair Location:** Kansas City**Repair # Description****Part #: 2542M85P01**

C&amp;I Clean &amp; Inspect

**ATA Code : 72-54-03: HIGH PRESSURE TURBINE STATOR STATIONARY SEAL****Repair Location:** Cincinnati**Repair # Description****Part #: 2521M52G02**

C&amp;I Clean &amp; Inspect

R002 Clinch Nut Replacement

**ATA Code : 72-54-05: NO. 4 BEARING FORWARD STATIONARY AIR SEAL****Repair Location:** Cincinnati**Repair # Description****Part #: 2542M94P01 2542M94P02**

C&amp;I Clean &amp; Inspect

SPM Blend General Blend

**ATA Code : 72-54-06: NO. 4 BEARING FORWARD STATIONARY OIL SEAL****Repair Location:** Cincinnati**Repair # Description****Part #: 2542M94P01 2542M94P02**

C&amp;I Clean &amp; Inspect

**ATA Code : 72-54-09: NO. 4 BEARING STATIONARY OIL SEAL****Repair Location:** Kansas City

**Repair #      Description****Part #:**    2542M86P01 2722M19P01 2797M16P01

C&amp;I            Clean &amp; Inspect

**ATA Code :    72-56-20: LOW PRESSURE TURBINE STAGE 1 NOZZLE SEGMENTS****Repair Location:**    Cork**Repair #      Description****Part #:**    364-058-810-0 364-058-910-0 364-059-010-0

C&amp;I            Clean &amp; Inspect

R001          Vapor Phase Aluminide Coating Removal and Replacement

R002          Oxides Removal

R003          Gaspath Areas Check

**ATA Code :    72-57-41: LOW PRESSURE TURBINE SHAFT****Repair Location:**    Cincinnati**Repair #      Description****Part #:**    364-035-610-0

C&amp;I            Clean &amp; Inspect

R001          Coating Replacement

**ATA Code :    72-57-42: FRONT ROTATING SEAL****Repair Location:**    Kansas City**Repair #      Description****Part #:**    364-087-401-0

C&amp;I            Clean &amp; Inspect

**ATA Code :    72-58-01: LOW PRESSURE TURBINE CASE****Repair Location:**    Cincinnati**Repair #      Description****Part #:**    364-600-805-0

C&amp;I            Clean &amp; Inspect

R001          Stage 2 to 6 Borescope Ports Adapter Replacement

R003          Pins Replacement

R004          Brackets and Rivets Replacement

**ATA Code :    72-58-21: LOW PRESSURE TURBINE STAGE 2 TO 4 BLADES****Repair Location:**    Palm City**Repair #      Description****Part #:**    364-023-120-0 364-023-230-0 364-023-320-0 364-023-720-0 364-023-820-0  
364-023-920-0

C&amp;I            Clean &amp; Inspect

R001          Blend Airfoil (Stage 2)

**ATA Code :    72-58-23: LOW PRESSURE TURBINE STAGE 2 NOZZLE SEGMENTS**

**Repair Location:** Cork**Repair #**      **Description****Part #:**    364-025-632-0 364-025-640-0 364-025-645-0 364-026-132-0 364-026-140-0  
364-026-145-0

C&amp;I            Clean and Inspect

R005           Gaspath Area Check

**ATA Code : 72-58-24: LOW PRESSURE TURBINE STAGE 3 NOZZLE SEGMENTS****Repair Location:** Cork**Repair #**      **Description****Part #:**    364-600-822-0 364-600-824-0 364-600-825-0

C&amp;I            Clean &amp; Inspect

R003           Leading Edge and Trailing Edge Blend Repair

**ATA Code : 72-58-41: LOW PRESSURE TURBINE STAGE 1 DISK****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    364-021-020-0 364-021-021-0 364-021-030-0 364-021-031-0 364-021-032-0

C&amp;I            Clean &amp; Inspect

**ATA Code : 72-59-08: TURBINE REAR VANE****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    364-037-210-0 364-037-220-0 364-037-221-0 364-037-222-0 364-037-225-0

C&amp;I            Clean &amp; Inspect

R001           Transient Bleed Valve Key-Locked Inserts Replacement

SB-72-0359   Replacement Of The Drains

**ATA Code : 72-61-41: PINION BEVEL GEAR****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    2542M61G01

C&amp;I            Clean &amp; Inspect

R002           Oil Seal Replacement

**ATA Code : 79-21-45: EDUCTOR VALVE****Repair Location:** Cincinnati**Repair #**      **Description****Part #:**    362-075-502-0 63292058-2

OVERHAUL    Overhaul

TEST           Test

**ATA Code : 80-11-15: VALVE AIR STARTER****Repair Location:** Fort Myers**Repair #**      **Description**

**Part #: 2496M44P01 2496M44P03 2496M44P04 2496M44P05 2496M44P06**

**63216083-1 63216083-2 63216083-3 63216083-4 63216083-5**

OVERHAUL Overhaul

TEST Test